

DAM LEVELS 07th NOVEMBER, 2022

| Name of Dam | River | Full Supply Storage Million Cubic meters | Percentage Storage (%) 31 st October, 2022 | Percentage Storage (%) 07 th November, 2022 |
|-------------|---------------|---|--|---|
| Mnjoli | Black Mbuluzi | 177 | 96.08 | 96.80 |
| Lubovane | Great Usuthu | 155 | 100.00 | 100.52 |
| Maguga | Komati | 332 | 88.94 | 90.44 |
| Hawane | Black Mbuluzi | 2.75 | 95.00 | 98.00 |
| Luphohlo | Lusushwana | 23.6 | 66.00 | 56.00 |

COMMENTS:

Water storage levels in all major dams looks good except for Luphohlo dam which has significantly decreased to 56%. The rains that were received in the past few days made a slight increase in some dams. Lubovane dam is currently above its full capacity, standing at 100.52%, while Mnjoli and Hawane dam are above 95%. Maguga dam is standing at 90%

The rainy season has started and it is anticipated that the dams water storage levels will increase and its most likely that the dams will start spilling. The nation is urged to avoid inundated areas and flooded crossings. The Ministry will continue to monitor the water situation in the country and keep the nation updated.

